



3540 SE 28th Avenue Portland, Oregon 97202

Oregon 503.234.2118  
Washington 360.750.0611  
Fax 503.331.7133

[www.soilsolutionsenvironmental.com](http://www.soilsolutionsenvironmental.com)

## Heating Oil Tank Soil Sample Statement

August 16, 2019

Property Owner: Tara Stahlberg  
Site Address: 3018 SE 169<sup>th</sup> Ave  
Portland, OR 97236

- Soil Solutions was contracted to investigate the soil beneath an underground residential heating oil storage tank at the above address.
- On August 15, 2019, a 500-gallon underground heating oil tank was located on the north side of the house. The tank was laying in a north-south orientation with the top of the tank approximately 1.1 feet below the ground surface and the bottom of the tank approximately 4.9 feet below the ground surface.
- Soil Solutions collected two samples from the tank in accordance with OAR-340-177. The samples were collected from the north and south ends of the tank at 4.9 to 6.9 feet below the ground surface.
- These samples were submitted to Friedman and Bruya Laboratory in Seattle, Washington to be analyzed for the NWTPH-Dx test. A copy of the laboratory report is attached, and the results are summarized below.

Sample Location	Laboratory ID Number	Laboratory Results
S1@4.9'-6.9'	908322-01	ND
S2@4.9'-6.9'	908322-02	ND

*\*ND= Not Detected; ppm= parts per million; bgs=below ground surface*

- The results suggest that a release to the environment has not occurred. This investigation conducted by Soil Solutions is only a representation of the soil conditions surrounding the tank for the locations and depths indicated above. In accordance with OAR-340-177, and with our agreement with the client, Soil Solutions has performed an investigation, which shall not be construed as a guaranteed absence of contamination.